OBEX OBEX

CSD/NPIC 373/64
5 DECEMBER 1964
PAGE 2 OF 5
COPY 2 OF 8

HICHWAY BRIDGE TCHEPONE AREA, LAOS 1642N 10613E

(SHE NPIC BRIEFING BOARD J-5982 FOR COMPARISON)

(SEE NPIC BRIEFING BOARD 3-5982 FOR COMPARISON)	
1. FIRST REVEALED	25X1
DAMAGE TO THE EASTERN SPAN OF THE FOUR-SPAN, STEEL-TRUSS	
ROUTE 9 HIGHWAY BRIDGE NEAR TCHEPONE.	25X1
REVEALED THAT THE EASTERN SPAN OF THE BRIDGE	25X1
WAS PARTIALLY COLLAPSED, PREVENTING VEHICULAR TRAFFIC FROM	
CROSSING THE SE BAN HIENG (RIVER) AT ROUTE 9. FLOODING ACTION	
WAS APPARENT ON BOTH BANKS OF THE RIVER. THERE WAS NO	
INDICATION OF ATTEMPTS TO FORD THE AREA.	
2. REVEALED A NEW	25X1
ROAD BY-PASS APPROXIMATELY 0.2 NM EAST OF THE BRIDGE CONNECTING	
ROUTE 9 WITH THE PARTIALLY-COLLAPSED EASTERN SPAN OF THE	
BRIDGE. THE BRIDGE APPEARED TO BE SERVICEABLE FOR VEHICULAR	
TRAFFIC.	
, REVEALS NO CHANGE	25 <b>X</b> 1
IN THE HIGHWAY BRIDGE ON ROUTE 9, LOCATED 1.4 NM NORTHWEST	
OF TCHEPONE, SINCE PHOTOGRAPHY THIS GRAPHIC	25X1
IS AN EXAMPLE OF THE NEW A-5C CAMERA SYSTEM INITIATED ON	
·	25X1
4. AREA HAS BEEN PREVIOUSLY COVERED BY NUMEROUS COLD	
TALE, LUCKY DRAGON,	25X1
SELECT SEC. 400.0	25X1

